

PURCHASING POLICY EXCEPTION FORM

FROM:

DATE: 8/16/24
DEPARTMENT: Fleet Management
VENDOR: Dynamic Auto Body Integrity Auto Group of Hernando
DEPT DIRECTOR/
MGR SIGNATURE:  DATE: 8/19/24

Amount of Invoice: \$21,409.00 Invoice Date: 8/5/24

The attached request for disbursement does not appear to be in compliance with County Purchasing Policy, for the following reason:

Repairs to vehicle #22798 (camera truck) after accident. Original estimate not forwarded to the Finance Coordinator therefore a purchase order was not completed. Email address now on file with Dynamic to ensure the Finance Coordinator receives all estimates.

Please forward all documentation with this form attached, and letter of explanation, to the Chief Procurement Officer.


TO: CHIEF PROCUREMENT OFFICER
Please review, and upon approval, forward to County Administration.

 Date: 8/22/2024

Resolution: Approved.

To process this disbursement, the request must be approved by the County Administrator.

TO: COUNTY ADMINISTRATOR
Please review, and upon approval, forward to the Finance Department for processing.
APPROVED FOR PAYMENT:

COUNTY ADMINISTRATOR (or designee): 
DATE: 8/29/24

APPROVED FOR PAYMENT:
FINANCE DIRECTOR/
ASST. FINANCE DIRECTOR

APPROVED
By Joshua Stringfellow at 8:26 am, Sep 16, 2024

Date: _____

Estimate
Invoice

Dynamic Auto Body

16288 Cortez Blvd.
Brooksville FL, 34601

Phone: 352-797-0449

Prepared by:

Matthew Mulvaney

Florida Registration# MV-54316

DATE

8/16/2024

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:
 I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100.
 I REQUEST A WRITTEN ESTIMATE.
 I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$ _____.
 THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.
 I DO NOT REQUEST A WRITTEN ESTIMATE
 SIGNED: _____ DATE: _____

OWNER INFO

3525406289

NAME_Hernando County Fleet

PHONE

CELL: _____

WORK: _____

ADDRESS: _____

CAR INFO:

MAKE: 2021 Ford f-550

MODEL: _____

Year:

Paint Code:

TAG: _____

MILES: _____

Vin#

1FDUF5GT0KEE60886

The Following repairs are requested to done.

Travelers Claim # FZD6989001

U/Used R/Rebuild NC/No Chg. Warranty RD/Reduced/Warranty

Qty:	Part No.	Description	Price	Extend

Parts: _____
 Labor: _____
 Paint _____
 Add. Cost _____
 Haz fee: _____
 Subtotal: _____
 Tax: _____
 Grand Total **\$21,409.00**

This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. **FS403.718mandates a \$1.00 fee for each new tire sold in the State of Florida. *FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.

Estimate is good for 30 days. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with the necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a teardown and reassembly fee of \$ _____ will be applied.

X _____ **Date** _____

Payment Method

Cash
Check# _____
Visa or Mastercard

Work completed by Matt Mulvaney

Date _____ Work aproved by _____

TRAVELERS - THE TRAVELERS INDEMNITY COMPANY

Mid-Atlantic Claim Center (BI-007)

Request Supplements at <https://supplements.travelers.com>

PO Box 430

Buffalo, NY 14240

Phone: (800) 842-9897

Claim #:

Workfile ID:

FZD6989001

b0f50c57

Supplement of Record 3 Summary

Written By: STEPHANIE WILLIAMS, 8/5/2024 11:57:38 AM
Adjuster: GAMAL EL-DIN, SHERRINE SABER, (484) 878-6287 Evening

Insured: HERNANDO COUNTY BD OF CTY COMM
Owner Policy #: CT501PEHK8100B16605
Claim #: FZD6989001
Type of Loss: Collision
Date of Loss: 12/13/2023 12:00 AM
Days to Repair: 19
Point of Impact: 12 Front
Deductible: 1000.00

Owner (Insured): HERNANDO COUNTY BD OF CTY COMM
15470 FLIGHT PATH DRIVE
BROOKSVILLE, FL 34604
(352) 540-6289 Evening

Inspection Location: 1525 E JEFFERSON ST
BROOKSVILLE, FL 34601-0000
Virtual
(352) 540-6289 Day

Appraiser Information: swillia1@travelers.com
(813) 394-0964

Repair Facility: DYNAMIC AUTO BODY
16288 CORTEZ BLVD
BROOKSVILLE, FL 34601
(352) 797-0449 Business

VEHICLE

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

VIN: 1FDUF5GTPKEE60886
License: TI1264
State: FL
Production Date: 05/2019
Odometer: 6455
Condition:
Interior Color:
Exterior Color: White

TRANSMISSION	Intermittent Wipers	SAFETY	Reclining/Lounge Seats
Automatic Transmission	Tilt Wheel	Drivers Side Air Bag	WHEELS
4 Wheel Drive	Message Center	Passenger Air Bag	Styled Steel Wheels
POWER	Steering Wheel Touch Controls	Anti-Lock Brakes (4)	PAINT
Power Steering	Telescopic Wheel	4 Wheel Disc Brakes	Clear Coat Paint
Power Brakes	Backup Camera	Traction Control	OTHER
DECOR	Remote Starter	Stability Control	California Emissions
Dual Mirrors	RADIO	Front Side Impact Air Bags	TRUCK
Tinted Glass	AM Radio	Head/Curtain Air Bags	Rear Step Bumper
Overhead Console	FM Radio	Hands Free Device	Trailer Hitch
CONVENIENCE	Stereo	Positraction	Trailer Package
Air Conditioning	Search/Seek	SEATS	Dual Rear Wheels

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	HE4- Van/Box Truck		1			
2	#	THE VEHICLE IS A 2021 FORD F550, SAME PARTS DECODED		1			
3	# S01	CORRECT VIN #1FDUF5GT0KEE60886		1			
4	# S01						
5	FRONT BUMPER						
6		O/H front bumper				4.3	
7	* S02	Repl Bumper dual rear wheels w/o fog lamps	LC3Z17757B	1	<u>1,128.82</u>	Incl.	
		NOTE: Supplement for the PPD					
8	R&I	License bracket single rear wheels	LC3Z17A385AB			0.3	
9	Repl	Step pad	LC3Z17C829AA	1	47.85	Incl.	
10	* S02	Repl Valance 4WD	LC3Z17626AA	1	<u>192.98</u>	Incl.	
		NOTE: Supplement for PPD					
11	* S02	Repl RT Air duct w/o distance sensor	LC3Z8310G	1	<u>71.90</u>	Incl.	
12	* S02	Repl LT Air duct w/o distance sensor	LC3Z8311D	1	<u>72.75</u>	Incl.	
13	GRILLE						
14	* S02	Repl Grille assy chrome	LC3Z8200BA	1	<u>304.45</u>	Incl.	
		NOTE: Supplement for PPD Grill					
15	* S02	Repl Emblem w/o front camera	LC3Z8213A	1	<u>85.77</u>	0.1	
		NOTE: Supplement for PPD					
16	FRONT LAMPS						
17	* S02	Repl RT Headlamp assy from 06/18/2018 w/o black trim	LC3Z13008L	1	<u>811.78</u>	Incl.	
		NOTE: supplement for PPD					
18		Aim headlamps				0.5	
19	* S02	Repl LT Headlamp assy from 06/18/2018 w/o black trim	LC3Z13008M	1	<u>826.83</u>	Incl.	
		NOTE: supplement for PPD					
20	# S02	Rpr wiring harness repairs				2.0	
21	RADIATOR SUPPORT						
22	* S02	Repl Mount panel	LC3Z88455B	1	<u>277.23</u>	1.6	
23	S02	Repl Lower tie bar (ALU)	HC3Z16139A	1	181.37 s	4.5	0.9
24	* S02	Repl Upper tie bar (ALU)	LC3Z16138A	1	<u>445.93</u>	1.2	1.1
		NOTE: supplement for PPD					
25	S02	Overlap Minor Panel					-0.2
26	* S02	Repl Sight shield 6.7 liter	LC3Z19E525F	1	<u>118.33</u>	Incl.	
		NOTE: supplement for PPD called a deflector					
27	S02	Repl RT Air deflector 6.7 liter	LC3Z8310J	1	18.32	Incl.	

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

28	S02	Repl	Air shield 6.7 liter all	NOT LISTED	1		0.4	
29	S02	Repl	Lower deflector 6.7 liter	HC3Z8310K	1	49.45	Incl.	
30	S02	Repl	LT Air deflector 6.7 liter	NOT LISTED	1		Incl.	
31	S02	Repl	RT Inner shield 6.7 liter	HC3Z8327E	1	15.45	Incl.	
32	S02	Repl	LT Inner shield 6.7 liter	HC3Z8327F	1	16.68	Incl.	
33	COOLING							
34	*	S02	Repl Radiator	LC3Z8005C	1	<u>944.38</u> m	4.8	
			NOTE: supplement for PPD					
35	*	S02	Repl Aux radiator	LC3Z8005A	1	<u>595.88</u> m	0.4	
36			Repl Upper shroud	LC3Z8146F	1	268.47	Incl.	
37	S02	Repl	Fan blade dual rear wheels	LC3Z8600A	1	200.00 m	Incl.	
38	S02	Repl	Air guide	HC3Z8B614B	1	323.20	0.3	
39	S02	Repl	Fan clutch dual rear wheels	LC3Z8A616E	1	660.00 m	Incl.	
40	S02	Repl	Serpentine belt	LC3Z8620G	1	88.00 m	0.8 M	
41	S02	Repl	Idler pulley	LC3Z8678D	1	58.18 m	0.2 M	
42	S02	Repl	P/S cooler	PC3Z3D746B	1	185.00 m	0.7 M	
43	S02	R&I	Trans cooler	LC3Z7869A		m	0.7 M	
44	S02	Repl	Reservoir tank	LC3Z9600F	1	295.00 m	Incl.	
45	S02	Repl	Aux radiator	HC3Z8005E	1	595.88 m	Incl.	
46	S02	Repl	Reservoir	LC3Z8A080D	1	133.58 m	Incl.	
47	S02	Repl	Intercooler	HC3Z6K775A	1	416.67 m	1.4 M	
48	S02		Deduct for Overlap				-0.5 M	
49	S02	Repl	Outlet duct	LC3Z6F073A	1	200.00 m	0.2	
50	S03	Repl	Lower shroud	LC3Z8146C	1	235.90	Incl.	
51	S03	Repl	Connector hose	HC3Z8597C	1	127.27 m	0.4	
52	S03	Repl	Connector hose	HC3Z18B402C	1	36.67 m	0.2	
53	AIR CONDITIONER & HEATER							
54	*	S02	Repl Condenser	HC3Z19712E	1	<u>327.27</u> m	1.1	
			NOTE: Supplement for PPD					
55			AC Service evacuate & recharge			m	1.4 M	
56			AC Service refrigerant recovery			m	0.4 M	
57	S02	Repl	Hose & tube assy	LC3Z19972B	1	127.27 m	0.8 M	
58	S03	Repl	AC tube	HC3Z19E631A	1	60.00		
59	HOOD							
60	*	S02	Repl Hood (ALU)	LC3Z16612C	1	<u>945.48</u>	2.2 3.2	
			NOTE: supplement is for PPD					
61			Add for Underside(Complete)				1.6	
62	*	S02	Repl Latch w/o theft	HC3Z16700G	1	<u>99.10</u>	0.3	
			NOTE: supplement for PPD					
63	S02	Repl	RT Hinge	HC3Z16796B	1	80.73	0.3 0.5	
64	S02		Overlap Minor Panel				-0.2	
65	S02	Repl	LT Hinge	HC3Z16797B	1	81.78	0.3 0.5	
66	S02		Overlap Minor Panel				-0.2	
67	FENDER							

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

68	*	S02	Repl	RT Fender w/wheel opening mldg (ALU)	LC3Z16005B	1	<u>370.28</u>	3.5	2.6
69				Overlap Major Adj. Panel					-0.4
70				Add for Edging					0.5
71	*	S02	Repl	LT Fender w/wheel opening mldg (ALU)	LC3Z16006B	1	<u>372.60</u>	3.5	2.6
72				NOTE: supplement is for PPD					
73				Overlap Major Adj. Panel					-0.4
74	*	S02	Repl	RT Nameplate "F-550 XL"	HC3Z16720AC	1	<u>28.83</u>	Ind.	0.5
75	*	S02	Repl	LT Nameplate "F-550 XL"	HC3Z16720AD	1	<u>28.83</u>	Ind.	
76			R&I	RT Wheel opng mldg dual rear whls	HC3Z16038AD			Ind.	
77			R&I	LT Wheel opng mldg dual rear whls	HC3Z16039AD			Ind.	
78			R&I	RT Fender liner XL, XLT	LC3Z16102E			Ind.	
79			R&I	LT Fender liner XL, XLT	HC3Z16103F			Ind.	
80		S02	Repl	RT Upper rail assy (HSS)	LC3Z16C274A	1	257.33 s	5.8	1.4
81		S02		Overlap Major Non-Adj. Panel					-0.2
82		S02		Deduct for Overlap				-1.5	
83	#	S02	Rpr	Pre pul time to the hinge cowl area on each side upper rail				2.0	
84		S02	Repl	LT Upper rail assy (HSS)	HC3Z16C275A	1	215.87 s	5.8	1.4
85		S02		Overlap Major Non-Adj. Panel					-0.2
86		S02		Deduct for Overlap				-1.5	
87		S02	Repl	RT Lower tie bar (HSS)	HC3Z16B168A	1	36.20 s	3.2	0.7
88		S02		Overlap Minor Panel					-0.2
89		S02	Repl	LT Lower tie bar (HSS)	HC3Z16B168B	1	39.40 s	3.2	0.7
90		S02		Overlap Minor Panel					-0.2
91		ELECTRICAL							
92		S02	Repl	LT Battery	BXT65750	1	169.95 m	0.5	
93		S02	Repl	Control module	NC3Z2C219A	1	483.08 m	0.6 M	
94		S03	Repl	RT Battery tray	HC3Z10732A	1	84.17	0.3	
95		ENGINE							
96		S02	Repl	Air cleaner assy	LC3Z9600G	1	565.00 m	0.6	
97		S02	Repl	Inlet hose	LC3Z9B659B	1	185.00		
98		S02	Repl	Inlet tube	LC3Z9C675C	1	98.67	Ind.	
99		S02	Repl	Air inlet tube	LC3Z9C675A	1	70.17 m	Ind.	
100		WINDSHIELD							
101		S02	Repl	Washer reservoir	HC3Z17618B	1	210.91		
102		FRONT DOOR							
103	*	S02	Rpr	RT Outer panel (ALU)	FL3Z1620200A			<u>1.0</u>	2.6

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

104			Overlap Major Adj. Panel						-0.4	
105	R&I		RT Belt molding black	FL3Z1521452E				0.3		
106	R&I		LT Belt molding black	FL3Z1521453D				0.3		
107	R&I		RT Applique XL, XLT regular cab w/o keyless pad	FL3Z1520554AD				0.3		
108	R&I		LT Applique XL, XLT regular cab w/o keyless pad	FL3Z1520555AD				0.3		
109	*	R&I	RT Nameplate "6.7L"	HC3Z9942528C				<u>0.2</u>		
110	*	R&I	LT Nameplate "6.7L"	HC3Z9942528D				<u>0.2</u>		
111	*	R&I	RT Nameplate "POWER STROKE"	HC3Z9942528E				<u>0.2</u>		
112	*	R&I	LT Nameplate "POWER STROKE"	HC3Z9942528F				<u>0.2</u>		
113		R&I	RT R&I mirror	HC3Z17682CA				0.4		
114		R&I	LT R&I mirror	HC3Z17683BA				0.4		
115		R&I	RT Run channel	FL3Z1521596H				0.2		
116		R&I	LT Run channel	FL3Z1521597E				0.2		
117		R&I	RT R&I trim panel	LC3Z2823942AA				0.6		
118		R&I	RT Handle, outside black w/o cylinder	JC3Z2522404BC				0.7		
119	*	R&I	LT Handle, outside black w/o cylinder	NOT USED				<u>0.7</u>		
120		R&I	LT R&I trim panel	LC3Z2823943AA				0.6		
121	*	S02	Rpr LT Outer panel (ALU)	FL3Z1620201A				<u>1.0</u>	2.6	
122		S02	Overlap Major Adj. Panel						-0.4	
123		S02	Clear Coat						2.5	
124	VEHICLE DIAGNOSTICS									
125	*		Rpr Pre-repair scan				m	<u>0.5</u>	M	
126	*		Rpr Post-repair scan				m	<u>0.5</u>	M	
127	MISCELLANEOUS OPERATIONS									
128	*		Repl Cover car/bag		1	5.00		0.2		
129	#		Rpr D&R Battery					0.2		
130	#		Rpr Set Up & Measure					2.0		
131	#		Rpr Unibody Frame Repair					2.0	F	
132	#	S02	Rpr brake lines straghtening					2.0		
133	#	S03	Repl BOLT AND WASHER ASY, PART #W7177609439		1	9.00				
134	#	S03	Repl PUMP ASY - Part #JC3Z3A674C		1	498.18				
135	#	S03	Subl Sublet Invoice -Mobile Power NOTE: invoice from Mobile POver this is for aftermarket pully		1	224.74	X			
136	#	S03	Subl Sublet invoice - scans, ac service +20% NOTE: Sublet invoice from Complete Auto Care this is for ac service, scans plus markup		1	515.89	X			
							SUBTOTALS	16,220.70	72.5	22.9

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			15,480.07
Body Labor	63.0 hrs @	\$ 55.00 /hr	3,465.00
Paint Labor	22.9 hrs @	\$ 55.00 /hr	1,259.50
Mechanical Labor	7.5 hrs @	\$ 70.00 /hr	525.00
Frame Labor	2.0 hrs @	\$ 50.00 /hr	100.00
Paint Supplies	23.3 hrs @	\$ 36.00 /hr	838.80
Miscellaneous			740.63
Subtotal			22,409.00
Total Cost of Repairs			22,409.00
Deductible			1,000.00
Total Adjustments			1,000.00
Net Cost of Repairs			21,409.00

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Added Items							
50	S03	Repl Lower shroud	LC3Z8146C	1	235.90	Incl.	
51	S03	Repl Connector hose	HC3Z8597C	1	127.27 m	0.4	
52	S03	Repl Connector hose	HC3Z18B402C	1	36.67 m	0.2	
58	S03	Repl AC tube	HC3Z19E631A	1	60.00		
94	S03	Repl RT Battery tray	HC3Z10732A	1	84.17	0.3	
133	#	S03 Repl BOLT AND WASHER ASY, PART #W717760s439		1	9.00		
134	#	S03 Repl PUMP ASY - Part #JC3Z3A674C		1	498.18		
135	#	S03 Subl Sublet Invoice -Mobile Power NOTE: invoice from Mobile POver this is for aftermarket pully		1	224.74 X		
136	#	S03 Subl Sublet invoice - scans, ac service +20% NOTE: Sublet invoice from Complete Auto Care this is for ac service, scans plus markup		1	515.89 X		
SUBTOTALS					1,791.82	0.9	0.0

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			1,051.19
Body Labor	0.9 hrs @	\$ 55.00 /hr	49.50
Paint Supplies			0.00
Miscellaneous			740.63
Subtotal			1,841.32
Total Supplement Amount			1,841.32
NET COST OF SUPPLEMENT			1,841.32

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	14,851.90	STEPHANIE WILLIAMS
Supplement S01	0.00	STEPHANIE WILLIAMS
Supplement S02	5,715.78	STEPHANIE WILLIAMS
Supplement S03	1,841.32	STEPHANIE WILLIAMS
Workfile Total:	\$ 22,409.00	
TOTAL ADJUSTMENTS:	\$ 1,000.00	
NET COST OF REPAIRS:	\$ 21,409.00	

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle. In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO INJURE, DEFRAUD, OR DECEIVE ANY INSURER FILES A STATEMENT OF CLAIM OR AN APPLICATION CONTAINING ANY FALSE, INCOMPLETE, OR MISLEADING INFORMATION IS GUILTY OF A FELONY OF THE THIRD DEGREE (FLORIDA STATUTES TITLE XLVI, CHAPTER 817.234). FAILURE TO USE THE INSURANCE PROCEEDS IN ACCORDANCE WITH THE SECURITY AGREEMENT, IF ANY, COULD BE A VIOLATION OF S. 812.014, FLORIDA STATUTES. IF YOU HAVE ANY QUESTIONS, CONTACT YOUR LENDING INSTITUTION. IF A CHARGE FOR SHOP SUPPLIES OR HAZARDOUS OR OTHER WASTE REMOVAL IS INCLUDED ON THIS ESTIMATE, PLEASE NOTE THE FOLLOWING: "THIS CHARGE REPRESENTS COSTS AND PROFITS TO THE MOTOR VEHICLE REPAIR FACILITY FOR MISCELLANEOUS SHOP SUPPLIES OR WASTE DISPOSAL." IF A CHARGE FOR NEW TIRES OR A NEW OR REMANUFACTURED LEAD-ACID BATTERY IS INCLUDED ON THIS ESTIMATE, PLEASE NOTE THE FOLLOWING: A \$1.00 FEE FOR EACH NEW MOTOR VEHICLE TIRE SOLD AT RETAIL IS IMPOSED ON ANY PERSON ENGAGING IN THE BUSINESS OF MAKING RETAIL SALES OF NEW MOTOR VEHICLE TIRES WITHIN THE STATE OF FLORIDA. FLORIDA STATUTES TITLE XXIX CHAPTER 403.718. A \$1.50 FEE FOR EACH NEW OR REMANUFACTURED LEAD-ACID BATTERY SOLD AT RETAIL IS IMPOSED ON ANY PERSON ENGAGING IN THE BUSINESS OF MAKING RETAIL SALES OF NEW OR REMANUFACTURED LEAD-ACID BATTERIES WITHIN THE STATE OF FLORIDA. FLORIDA STATUTES TITLE XXIX 403.7185.

Supplement of Record 3 Summary

2021 FORD Super Duty F-350 w/Dual Rear Wheels XL Supercab 4WD w/8' Box 4D LONG 8-6.7L Turbocharged Diesel Diesel Direct Injection White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2MN18, CCC Data Date 07/17/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.