



PROCUREMENT DEPARTMENT

15470 FLIGHT PATH DRIVE ♦ BROOKSVILLE, FLORIDA 34604
P 352.754.4020 ♦ F 352.754.4199 ♦ W www.HernandoCounty.us

AMENDMENT NO. ONE (1)

TO

CONTRACT NO. 23-TS00287/SF

FOR

Centrifuge Equipment Repair and Equipment Lease

The following changes, additions and/or deletions are hereby made a part of the Contract Documents for the **CONTRACT NO. 23-TS00287/SF**, located in Hernando County, as fully and completely as if the same were fully set forth therein:

- 1. Section eight (8) Pricing Proposal, is amended to read:

The Vendor/Contractor shall provide all labor and other resources necessary to provide the supplies, equipment and/or services in strict accordance with the specifications defined in this solicitation for the amounts specified in Exhibit C and *Exhibit D*, inclusive of overhead, profit, and any other costs.

There are no guarantees that the County will utilize any per year estimates and may exceed any estimates identified.

- 2. All other terms and conditions shall remain the same.

CENTRISYS CNP CORPORATION

BOARD OF COUNTY COMMISSIONERS
HERNANDO COUNTY

Authorized Signature

Beth Narverud
Chair, Hernando County Board of County Commissioners

11/30/2023

01-09-2024

Date

Date



Hernando County Utilities
Attn: Bruce Batten
15400 Wiscon Road
Brooksville, FL 34601

**PRELIMINARY REPAIR ESTIMATE OF CS21-4HC ROTATING ASSEMBLY AND
 2071D/F ROTODIFF**

Opp 13656

CENTRIFUGE REPAIR PRICING – MINOR

1. Dismantle, clean and inspect
2. Provide report with digital pictures
3. Replace bearings and seals
4. Hi-speed balance bowl
5. Hi-speed balance scroll
6. Reassemble

Total	\$ 26,500.00
--------------	---------------------

BACKDRIVE REPAIR – MINOR

1. Dismantle, clean and inspect
2. Replace bearings and seals
3. Reassemble
4. Test

Total	\$ 6,500.00
--------------	--------------------

SHIPPING

1. Shipping rotating assembly and rotodiff to and from site
 Estimated - will be invoiced at actual cost

Total	\$ 7,000.00
--------------	--------------------

Total Minor Repair	\$ 40,000.00
---------------------------	---------------------

F-7.5.1-007-02



CENTRIFUGE REPAIR PRICING – MAJOR

- 1. Dismantle, clean and inspect
- 2. Provide report with digital pictures
- 3. Replace bearings and seals
- 4. Replace worn/missing tiles (up to 40 tiles)
- 5. Replace broken nozzles
- 6. Repair flights
- 7. Repair feed chamber wear
- 8. Hi-speed balance bowl
- 9. Hi-speed balance scroll
- 10. Reassemble

Total	\$ 58,000.00
--------------	---------------------

BACKDRIVE REPAIR – MAJOR

- 1. Dismantle, clean and inspect
- 2. Replace bearings and seals
- 3. Replace transfer seal
- 4. Replace cam
- 5. Replace rotor
- 6. Reassemble
- 7. Test

Total	\$ 30,500.00
--------------	---------------------

SHIPPING

- 2. Shipping rotating assembly and rotodiff to and from site
Estimated - will be invoiced at actual cost

Total	\$ 7,000.00
--------------	--------------------

Total Major Repair	\$ 95,500.00
---------------------------	---------------------

F-7.5.1-007-02



TERMS:

Validity:	Valid for 30 days. Centrisys reserves the right to adjust this estimate
Terms:	Net 30
Delivery:	4-10 weeks ARO
FOB:	Kenosha, WI
Warranty:	6 months on repaired/replaced parts
Quote Prepared By:	George Kueppers
Dated:	11-3-23
Sent to:	Bruce Batten
E-mail Address:	bbatten@co.hernando.fl.us

F-7.5.1-007-02