

INTEGRITY LAND SOLUTIONS GROUP, INC. Professional Land Surveying & Mapping

12345 Centralia Rd./P.O. Box 6890 Spring Hill, FL 34611 Phone: (352) 428-2351 Fax: (352) 556-3993 Email: ILSG@tampabay.rr.com

WORK ORDER: 22 - 70 MAP DATE: 4/18/2022 SECTION: 29 TOWNSHIP: 22 S RANGE: 19 E

CERTIFIED TO THE FOLLOWING ONLY: Parcel ID: R29 422 19 0000 0150 0000

- CLEAN SLATE DEMO, INC.

Physical Address: @ MOBLEY RD.

PARENT TRACT DESCRIPTION: O.R. BOOK 3870 PAGE 1209 Commence at the Northwest comer of the Southwest 1/4 of Section 23, Township 22 South, Range 19 East, Hemanico County, Rother is there South 98 degrees 29 minutes 09 seconds East, allong the Horth line of the Southwest 1/4 of said Section 29, a distance of 1985.15 feet to the POINT OF BESIMENING for Treat-1; there Southwest 1/4 or seld section 2/3 a quarter or 1953.15 et al. of the 10-40 of 643.02 feet to the West maintained inglined-way line of Mobiley Road; thence South 01 degrees 10 minutes 55 seconds West, along said inglin-of-way line, a distance of 475.00 feet; thence North 03 degrees 24 minutes 95 seconds West, along said inglin-of-way line, a distance of 475.00 feet; thence North 03 degrees 24 minutes 95 seconds West, a distance of 642.65 feet; thence North 01 degrees 08 minutes 11 seconds East, a distance of 475.00 feet to the Point of

PARCEL " A "

엾

Commence at the NE corner of the SW 1/4 of Section 29, Township 22 South, Range 19 East, Hernando County, Florida, said point being monumented with a nail & disk stamped "PLS 3882". Go thence along the North line of said SW 1/4, N89°25'37"W, a distance of 17,71 feet to a point on the present, maintained West right-of-way line of "Mobiley Rd" and the POINT OF BEGINNING, said point being monumented with a 1/2" capped iron rod stamped "LB 5776". Thence along the said right-of-way line, run S01°10'55"W, a distance of 205,00 feet to a point; leaving said right-of-way line, run N89°26'05"W, a distance of 642,79 feet to a point on the West boundary line of that parcel as described in O.R. Book 3870 page 1209 of the Public Records of Hernando County, Florida; thence run along said West boundary line, N01°07'21"E, a distance of 205,00 feet to the NW corner of said parcel as described in O.R. Book 3870 page 1209; thence run along the North boundary line of said described parcel, S89°26'05"E, a distance of 643.01 feet (formerly S89°24'09"E, 643.02 feet) to the Point of Beginning.

PARCEL " B "

Commence at the NE corner of the SW 1/4 of Section 29, Township 22 South, Range 19 East, Hernando County, Florida, said point being monumented with a nail & disk stamped "PLS 3882". Go thence along the North line of said SW 1/4, N89°25'37"W, a distance of 17.71 feet to a point on the present, maintained West right-of-way line of "Mobiley Rd", said point being monumented with a 1/2" capped iron rod stamped "LB 5776". Thence along the said right-of-way line, run S01°10'55"W, a distance of 205.00 feet to the POINT OF BEGINNING; continue thence along said right-of-way line, S01°10'55"W, a distance of 269.84 feet to the SE corner of that parcel as described in O.R. Book 3870 page 1209 of the Public Records of Hernando County, Florida; thence run along South boundary line of said described parcel, N89°28'17"W, a distance of 642,52 feet (formerly N89°24'09"W, 642,65 feet) to the SW corner of said described parcel; thence run along the West boundary line of said described parcel, N01°07'21"E, a distance of 270.25 feet; thence run S89°26'05"E, a distance of 642,79 feet to the Point of Beginning.

CMP - Corrugated Metal Pipe EP - Edge of Pavement F - Derived from Field Ma F - Derived mon Held measurer FCIR - Found Capped Iron Rod FMND - Found Mag Nail & Disk GW - Guy Wire ID - Identification L# - Line Table Number Legend

- LB Land Surveyor Business LS Land Surveyor
- NCF No Climb Fence NE Northeast NW Northwest OHW - Overhead Wire O.R. - Official Records
- PLS Professional Land Surveyor POB Point of Beginning POC Point of Commencement PP Power Pole R Record Plat or Deed
- R/W Right-of-Way SCIR Set Capped Iron Rod

SE - Southeast SEC - Section SW - Southwest

න්

Abbreviations

Surveyor Notes

- Survey based on the description furnished by the Client and without benefit of a title search.
 Survey is subject to notes, statements, and notations shown
- 3. Underground utilities and subsurface improvements not located unless otherwise shown hereon.
 4. There are no visible encroachments unless otherwise shown
- hereon.

 5. Ownership of fences located on or near property line(s) was not determined by this Surveyor.
- The measured distance from existing improvement designated features, such as, but not limited to, proand/or other lines, or other existing improvements, are perpendicular unless otherwise shown hereon.
- 7. Gutters, overhangs, underground foundations and imigation systems are not located unless otherwise shown hereon.
- 8. The property shown hereon may be subject to Rules, Regulations, Ordinances and/or Jurisdictions of Local, State, and/ or Federal Agencies, Requirements of said Rules, Regulations, and/or the limits of said Jurisdictions were not determined by this Surveyor, unless otherwise shown hereon.
- 9. According to FEMA, FIRM map panel 12053C0191D dated According to FRM, FIRM map panel 1205SOSISID dated rehavany 02, 2012, anglest properly spears to line within Flood Zone(g): "X," "M," A. "Aff". Properly also lise within Administrative Frod Plans, Cortact, County for more elementarion, and the property of the property of the property of the Administrative Frod Plans, Cortact, County for more elementarion promising agency's website portals. The source and accuracy of the state was not determined by this Surveyor, relation, on this flood zone information is at the sole risk of those to whom it is certified.
 Learning shrom hereon are beased on the North Inc. SW 1/4, Section 29-22-19, Bearing: \$89°24'09"E is assumed by this \$1 and designated hereon by the graphical entry "BASIS" at aforestated bearing. The North arrow is assumed per bearing. 12. Subject property may be subject to Reservations, Restriction ments of Record and not of Record that an accurate title anquor payments for record and not or record up to the discovered search may disclose. Determination was not made by this Surveyor for the aforementioned and shall not be held liable in any way for damages caused as a result. 13, Held monuments found in place as set by previous surveyors,
- unless otherwise shown hereon,

 14. Any reproduction or photocopy of this map of survey, partially or
 in its entirety, is prohibited without the written consent and permissic
 of Integrity Land Solutions Group, Inc., and in such cases shall be

- considered not valid and of uncertified information only. In such case, reliance upon information is at the sole risk of user and Integrity Land Solutions Group, Inc., and/or its affiliates, will not be held liable in
- Solutions unselve over all any other purposes than what it was created for and shall be considered in such case, general information only and not valid. This map of survey is not to be used for design angler construction purposes without the expressed permiss the fight to be used. of Integrity Land Solutions Group, Inc., which reserves the right to deny any additional use of this map other than the purpose for which it was created. THIS IS NOT A SITE PLAN.
- Outlings Surveyor recepts not reportability for right of very, essement restrictions or other matters affecting this to land surveyed other than those rectical in the current deed analysis instruments of records furnished by the client affect their agents.
 This map of survey is solely from the NOTTHANSFERVALE. Integrity contribution to schown hereon and is NOTTHANSFERVALE. Integrity
- Land Solutions Group, Inc., assumes no responsibility for any and all lamages caused as a result of using this map contrary to at

FIELD MEASURE LINE INFORMATION NUM BEARING DISTANCE
L1 N89°25'37"W 17,71'

THIS CERTIFIES THAT A SURVEY OF THE PROPERTY DESCRIBED HEREON, WAS MADE UNDER MY SUPERVISION AND THAT THE SURVEY MEETS THE STANDARDS OF PRACTICE SET FORTH BY THE FLORIDA BOARD OF PROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTER 5J-17 FLORIDA ADMINISTRATIVE CODE, PURSUANT TO SECTION 472,027, FLORIDA STATUTES, AND THAT THE MAP HEREON IS A TRUE AND ACCURATE REPRESENTATION THEREOF, TO THE BEST OF MY KNOWLEDGE AND BELIEF.

Christian T. Gordon Digitally signed by Christian T. Gordon Date: 2022.05.16 13:26:19 - 04'00'

DATE OF LAST FIELD ACQUISITION: 4/12/2022

CHRISTIAN T. GORDON. Professional Surveyor & Mapper Florida Registration # 6191 Integrity Land Solutions Group, Inc. LB #8065

SHEET 1 OF 1

O- Set Monument - Found Monumen

± - More or Less

A - Found Monument

OFFICE USE ONLY: C:\SURVEYS\2022DWG\00-22\22-70\22-70,DWG

LAST PLOTTED: 4726/2022 FIeld Book: 40 Page(e): 40 Drawn By: CRC Checked By: CTG/AIP UNLESS IT BEARS THE SIGNATURE AND THE ORIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER, THIS DRAWING, SKETCH, PLAT, OR MAP IS FOR INFORMATIONAL PURPOSES ONLY AND IS NOT VALID.