



## Legislation Text

---

**File #:** 12045, **Version:** 1

---

### **TITLE**

Resolution Providing for Modification of Yield Condition at Intersection of Shoal Line Boulevard and Osowaw Boulevard to Full Stop Condition, Providing for Placement of Stop Sign

### **BRIEF OVERVIEW**

Triangle Park is located at the intersection of Shoal Line Boulevard and Osowaw Boulevard. Although the speed limits on Shoal Line and Osowaw Boulevard are 35 MPH around Triangle Park, the yield condition allows motorists to maintain their speed as they travel past the park. The stop condition will ensure the safety of the patrons at the park and prevent vehicles exiting Shoal Line Boulevard onto Osowaw Boulevard from merging into oncoming traffic.

Staff is recommending the existing yield sign be modified to a stop sign to enhance traffic safety at the intersection of Shoal Line Boulevard and Osowaw Boulevard.

### **FINANCIAL IMPACT**

Funding for materials and installation of a Stop sign is available in the following accounts:

- 1011-03081-510\* (Personal Services) \$200.00
- 1017-03233-530\* (Operating Expenses) \$300.00

### **LEGAL NOTE**

The Board is authorized to act on this matter pursuant to Chapter 316, Florida Statutes.

### **RECOMMENDATION**

It is recommended the Board adopt and authorize the Chairman's signature on the attached resolution providing for the modification of the yield condition to a full stop condition and providing for placement of a stop sign at the intersection of Shoal Line Boulevard and Osowaw Boulevard.