# PURCHASING POLICY EXCEPTION FORM

FROM: 4/30/24
DATE: 4/30/24 DEPARTMENT: Fleet Management
VENDOR: Ten-8
DEPT DIRECTOR/ MGR SIGNATURE: Bren de les les DATE: 4/30/24
Amount of Invoice: \$13,130.17 Invoice Date: 4/12/24
The attached request for disbursement does not appear to be in compliance with County Purchasing Policy, for the following reason:
see attached
Please forward all documentation with this form attached, and letter of explanation, to the Chief Procurement Officer.
TO: CHIEF PROCUREMENT OFFICER
Please review, and upon approval, forward to County Administration.
Call Ross - July Date: 3/10/2024
Resolution: Approved. Now that system issues caused by the network disruption are resolved the department should create a PO for the contract
that was awarded to perform these services.
To process this disbursement, the request must be approved by the County Administrator.
TO: COUNTY ADMINISTRATOR
Please review, and upon approval, forward to the Finance Department for processing.  APPROVED FOR PAYMENT:
COUNTY ADMINISTRATOR (or designee):  DATE: 3 (())()
APPROVED FOR PAYMENT:
FINANCE DIRECTOR/  APPROVED
ASST. FINANCE DIRECTOR By Joshua Stringfellow at 10:23 am, May 20, 2024 Date:

To:

Hernando County Purchasing

From:

Brenda Peshel, Fleet Manager

Date:

April 30, 2024

Subject:

Ten-8 #21404

On March 27,2024 Ten-8 was contacted for repairs needed on the ARFF truck (stryker) located at the airport. Due to emails being down a quote was not received. Since this is an emergency vehicle and the only apparatus of its kind in Hernando County repairs were completed. The certification of the equipment was also past due so this was completed at that time also.



BRADENTON, FL 34203 Phone: 800-228-8368 Fax: 941-756-2598

Invoice to:

**TEN-8 FIRE & SAFETY, LLC** 2904 59TH AVENUE DRIVE EAST

HERNANDO CO FLEET MAINTENANCE

1525 EAST JEFFERSON STREET

BROOKSVILLE FL 34601

21404

Original

**Service Invoice** 

Page Invoice No: Invoice Date

1310040192 04/12/24

Pyment Terms

30 DWOR

Customer No. PO Number

C00479 792328

Equipment Id.:

792328

VIN #:

10TADLJF5KA792328 Fire Truck

Description:

Veh. Miles:

1,539

Veh. Hours:

481

Approved:

USA							
No.	Description	Quantit	Price	Amount	Disc. %	Disc. Amt.	Total
COMPL	792328 WINDSHIELD WIPERS INTERMITTENT						
LABOR	LABOR	6.15	165.00	1,014.75			1,014.75
4202698	MODULE,PWR,CAB,BLK,DVEC,24V	1	957.34	957.34			957.34
SHOP	SHOP SUPPLIES	1	81.18	81.18			81.18
005	Diag. Wiper complant, Replaced customer wiper motor and ord motor	dered pass front PD	Q for low speed	d inop of wiper			
006	Subtotal:						2,053.27
COMPL	792328 WASHER FLUID TANK IS CRACKED				Midsell.		
LABOR	LABOR	1	165.00	165.00			165.00
3875406	TANK,WIPER,9.6L	1	95.03	95.03			95.03
SHOP	SHOP SUPPLIES	1	13.20	13.20			13.20
011	Replaced washer tank , fill and test operation.						
012	Subtotal:						273.23
COMPL	792328 CEL						
LABOR	LABOR	0.15	165.00	24.75	legi i sa baren Erranan		24.75
SHOP	SHOP SUPPLIES		4.00	1.98			1.98
	SHOP SUPPLIES		1.98	1.50			1.50
016	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.	red by an authorize	d Scania dealer	,No work		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.30
016	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this	red by an authorize	d Scania dealer	,No work		THE WAS A	26.73
	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.	red by an authorize	d Scania dealer	,No work		1000	
017 COMPL	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR	red by an authorize	d Scania dealer	,No work			
017 COMPL	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR RETRACTING STREAM TO FOG	red by an authorize repair as I am not	ed Scania dealer and authorized	,No work technician for		1000	26.73
017	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR RETRACTING STREAM TO FOG ** LABOR	red by an authorize repair as I am not 1	nd Scania dealer and authorized 165.00 13.20	,No work technician for 165.00 13.20			<b>26.73</b> 165.00
017 COMPL LABOR SHOP	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR RETRACTING STREAM TO FOG LABOR SHOP SUPPLIES  Customer supplied new fog nozzle motor for bumper turret, Re	red by an authorize repair as I am not 1	nd Scania dealer and authorized 165.00 13.20	,No work technician for 165.00 13.20			<b>26.73</b> 165.00
017 COMPL LABOR SHOP	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR RETRACTING STREAM TO FOG LABOR SHOP SUPPLIES  Customer supplied new fog nozzle motor for bumper turret, Retest operation.	red by an authorize repair as I am not 1	nd Scania dealer and authorized 165.00 13.20	,No work technician for 165.00 13.20			26.73 165.00 13.20
017 COMPL LABOR SHOP	Knox sensor code stored for high soot and will have to be clear performed an authorized scania dealer must come out for this scania I cannot clear codes for this complaint.  Subtotal:  792328 FRT BUMPER TURRET STICKS OCCASIONALLY WHEN EXT OR RETRACTING STREAM TO FOG LABOR SHOP SUPPLIES  Customer supplied new fog nozzle motor for bumper turret, Retest operation.  Subtotal:	red by an authorize repair as I am not 1	nd Scania dealer and authorized 165.00 13.20	,No work technician for 165.00 13.20			26.73 165.00 13.20

Fog stream nozzle was greased with incorrect grease and causing motor to not be able to change modes, Removed nozzle and clean old lithium grease and used a petroleum based grease to lube o-rings and fog nozzle and nozzle shaft for proper operation.



2904 59TH AVENUE DRIVE EAST BRADENTON, FL 34203 Phone: 800-228-8368 Fax: 941-756-2598

HERNANDO CO FLEET MAINTENANCE

1525 EAST JEFFERSON STREET

BROOKSVILLE FL 34601 USA

Original

**Service Invoice** 

Page

2/5

Invoice No:

1310040192

Invoice Date Pyment Terms 04/12/24 30 DWOR

Customer No.

C00479

PO Number

792328

Equipment Id.:

792328 10TADLJF5KA792328

VIN #: Description:

**Fire Truck** 

Veh. Miles: Veh. Hours: 1,539 481

Approved:

No.	Description	Quantit	Price	Amount	Disc. % Disc. Amt.	Total
027	Subtotal:					267.30
COMPL	792328 WHEN FLUFFING THE TANK, UNABLE TO VENT AND PRESSURE GAUGE DOES'T READ PSI					
LABOR	LABOR	4.5	165.00	742.50		742.50
3954045	VALVE,AIR,4-WAY,24V	1	269.13	269.13		269.13
SHOP	SHOP SUPPLIES	1	59.40	59.40		59.40
32	Diag vessel not pressurizing, Ordered a 24v Mac valve for replaced and fluff vessel to test operation.	nitrogen valve operati	on. Removed old	Mac valve and		
033	Subtotal:					1,071.03
COMPL	792328 CAPTAIN SIDE A/C VENT INOP					
ABOR	LABOR	0.5	165.00	82.50		82.50
8869094	AER-LOUVER,RECT BLK HOSE	1	117.20	117.20		117.20
БНОР	SHOP SUPPLIES	1	6.60	6.60		6.60
	Subtotal:					206.30
COMPL	792328 LEAK AT THE BOTTOM OF THE RELIEF DRAIN VALVE IN THE FRT					
LABOR	LABOR	1				
SHOP	SHOP SUPPLIES	1				
042	Subtotal:					0.00
COMPL	792328 QC CHECK					
LABOR	LABOR	1			*	
045	Subtotal:					0.00
COMPL	792328 ENG OIL SERVICE					
LABOR	LABOR	3	165.00	495.00		495.00
OTRMO-1540	SB-5G OTR 15W40 SYN BLEND 5 GAL	51	6.98	355.98		355.98
OTRMO-1540	SB-5G OTR 15W40 SYN BLEND 5 GAL	60	6.98	418.80		418.80
3093795	REPAIR KIT,OIL FILTER	1	158.07	158.07		158.07
4688963	FUEL FILTER	1	79.74	79.74		79.74
PF9829KIT	FUEL FILTER KIT	1	61.77	61.77		61.77
SHOP	SHOP SUPPLIES	1	39.60	39.60		39.60
054	Subtotal:					1,608.96
COMPL	792328 SERVICE TRANSFER CASE					
LABOR	LABOR	1.5	165.00	247.50		247.50



2904 59TH AVENUE DRIVE EAST BRADENTON, FL 34203 Phone: 800-228-8368 Fax: 941-756-2598

Invoice to:

HERNANDO CO FLEET MAINTENANCE

1525 EAST JEFFERSON STREET

BROOKSVILLE FL 34601

**USA** 

### Original

**Service Invoice** 

Page Invoice No:

3/5 1310040192

Invoice Date Pyment Terms 04/12/24 30 DWOR

Customer No.

C00479

PO Number Equipment Id.: 792328 792328

10TADLJF5KA792328

Description:

Fire Truck

Veh. Miles:

1,539

Veh. Hours:

481

Approved:

No.	Description	Quantit	Price	Amount	Disc. %	Disc. Amt.	Total
OTRMO-1540SB-5G	OTR 15W40 SYN BLEND 5 GAL	6	6.98	41.88			41.88
SHOP	SHOP SUPPLIES	1	19.80	19.80			19.80
)59 <b>Sub</b>	ototal:						309.18
COMPL	792328 FRT AND REAR DIFF SERVICE						
ABOR	LABOR	2	165.00	330.00			330.00
PTGL-80W90-55G	80W90 GEAR LUBE	21	8.40	176.40			176.40
БНОР	SHOP SUPPLIES	1	26.40	26.40			26.40
064 <b>Sub</b>	ototal:						532.80
COMPL	792328 STEERING SERVICE	* * * * * * * * * * * * * * * * * * * *					
ABOR	LABOR	1	165.00	165.00			165.00
8HR851	ELEMENT FILTER, TRANS PUMP.	1	58.00	58.00			58.00
HYDRAN 32	HYDRAN OIL #32	13	10.40	135.20			135.20
FP-BUCKET-KIT	BUCKET & LID COMBO	1	13.02	13.02			13.02
SHOP	SHOP SUPPLIES	1	13.20	13.20			13.20
071 Sub	ototal:						384.42
COMPL	792328 TRANS SERVICE						
ABOR	LABOR	3.5	165.00	577.50			577.50
PT9415-MPG KIT	TRANSMISSION FILTERS	1	79.11	79.11		2.3.777	79.11
PTAFT-SSP-5G	OTR ATF PREMIUM 5GAL	79	10.64	840.56			840.56
SHOP	SHOP SUPPLIES	1	46.20	46.20			46.20
077 Sub	ototal:						1,543.37
COMPL	792328 HYD GENERATOR SERVICE						
LABOR	LABOR	1	165.00	165.00			165.00
OIL-DEXRON III	DEXTRON III OIL -TES 389	17	5.19	88.23	-()		88.23
1340162	GENERATOR ELEMENT HYD FILTER	1	468.43	468.43			468.43
1340163	GASKET, ELEMENT HYD GENERATOR		196.96	196.96			196.96
DIL-DEXRON III	DEXTRON III OIL -TES 389	17	5.19	88.23			88.23
SHOP	SHOP SUPPLIES	1	13.20	13.20			13.20
085 <b>Sub</b>	ototal:		i e				1,020.05
COMPL	792328 DEF SERVICE						
ABOR	LABOR	0.5	165.00	82.50			82.50
JF106	SCR UREA FILTER	1	321.30	321.30			321.30



2904 59TH AVENUE DRIVE EAST BRADENTON, FL 34203 Phone: 800-228-8368 Fax: 941-756-2598

Invoice to:

HERNANDO CO FLEET MAINTENANCE

1525 EAST JEFFERSON STREET

BROOKSVILLE FL 34601

Original

**Service Invoice** 

Page

Invoice No:

1310040192

Invoice Date Pyment Terms 04/12/24 30 DWOR

Customer No.

C00479

PO Number

792328

Equipment Id.:

792328 10TADLJF5KA792328

VIN #: Description:

Fire Truck

Veh. Miles:

Veh. Hours:

1,539 481

Approved:

No.	Description	Quantit	Price	Amount	Disc. % Disc. Amt. Total
SHOP	SHOP SUPPLIES	- 1	6.60	6.60	6.60
090 <b>Su</b> t	ototal:				410.40
COMPL	792328 PWR DIVIDER SERVICE				
LABOR	LABOR	8	165.00	1,320.00	1,320.00
3283733	FILTER ELEMENT, SPIN-ON	1	218.97	218.97	218.97
SHOP	SHOP SUPPLIES	1	105.60	105.60	105.60
095 Sub	ototal:				1,644.57
COMPL	792328 COOLANT SERVICE				
LABOR	LABOR	2.5	165.00	412.50	412.50
COOLANT RED NOAT	COOLANT RED 50/50/ (NOAT)( ELC)	15	13.40	201.00	201.00
SHOP	SHOP SUPPLIES	1	33.00	33.00	33.00
100 Sub	ototal:				646.50
COMPL	792328 PLANETARY GEAR DRIVE				
LABOR	LABOR	3.5	165.00	577.50	577.50
SHOP	SHOP SUPPLIES	1	46.20	46.20	46.20
104 Perf	formed planetary drive wheel end service all 4 who	eel ends			
105 <b>Sub</b>	ototal:				623.70
Details				Subtotal:	\$ 12,800.01
ax Code	Tax % Net	Tax		Freight:	\$ 330.16
			•	Total Before Tax	\$ 13,130.17
		Chinalan T.	10	Total Tax Amoun	t: \$ 0.00
ditional Expenses:		Shipping Type:	- iÇ	Total Amount	\$ 13,130.17
Description	Net Tax Code Tax %	Tax Gross		-	
FREIGHT SER FL	330.16 FLHERNAN 6.500	0.00 330.16			



2904 59TH AVENUE DRIVE EAST BRADENTON, FL 34203 Phone: 800-228-8368 Fax: 941-756-2598

Invoice to:

HERNANDO CO FLEET MAINTENANCE

1525 EAST JEFFERSON STREET

BROOKSVILLE FL 34601 USA Original

**Service Invoice** 

Page

5/5

Invoice No:

1310040192

Invoice Date

Pyment Terms

04/12/24 30 DWOR

Customer No.

C00479

PO Number

792328 792328

Equipment Id.: VIN #:

10TADLJF5KA792328

Description:

Fire Truck

Veh. Miles:

1,539

Veh. Hours:

481

Approved:

Currency: \$